



100/120V Wiring

220/240V Wiring



* Shield must be cut and insulate on these sides

** Missing Pad, connect wire to C10 R11 Junction

Bias Setting: 45V on 5881/6L6 pins 5